


RDNet 5.6 Introduces Major XPS Firmware Update

Posted on October 21, 2026

RDNet 5.6 Introduces Major XPS Firmware Update



RDNet 5.6 is now available, introducing new XPS functionality, support for the new XPS 4K amplifier and speakers, bugfixes and an important firmware update for XPS Series amplifiers. The update includes a new bootloader designed to address XPS boot-related errors. The application firmware must be installed first, followed by the bootloader firmware.

RDNet 5.6 Introduces Major XPS Firmware Update

Read

more: https://www.rcf.it/en/-/rdnet-5.6-and-mandatory-xps-firmware-update?utm_source=rcf_newsletter&utm_medium=email&utm_campaign=Newsletter_generic

https://www.rcf.it/en/-/rdnet-5.6-and-mandatory-xps-firmware-update?utm_source=rcf_newsletter&utm_medium=email&utm_campaign=Newsletter_generic